



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 27, 2012

Reviewed: 

Mine Name: Rapunzel	Permit Number: S/023/0083
Operator Name: Earth's Partners	Inspection Date: April 26, 2012
Inspector(s): Wayne Western, Dana Dean	Time: 2:45 – 3:00 pm
Other Participants: None	Mine Status: ACT
Weather Condition: 70's windy, partly overcast sky	Last Inspection: August 20, 2006
Bond Renewal Date: August 17, 2007	Bond Amount: \$1,000 BLM – State wide bond
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: less than 1 ton	Acreage: 2 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The permit is current. The Permittee claims that they collect a limited amount of material..

The permit fees are current.

The bond renewal is passed due. The Division should require additional bond.

The site is in a remote area and there is little evidence that the site is visited by the public.


Conclusions and Recommendations:

The Division should require that the Permittee post more bond.

Directions to Site:

The general directions to the site go on the Weis Highway and then turn north Erickson Pass Road. There are several dirt roads that lead to the mine.

Inspector's Signature

A handwritten signature in cursive script, appearing to read "Wayne Wester", written over a horizontal line.

WHW:

cc: (OPERATOR)

Jerry Mansfield BLM

O:\M023-Juab\S0230083-Rapunzel\inspections\INSP-04262012.doc



